

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VIII

999 18th STREET SUITE 500
DENVER COLORADO 80202 2466

1709 RF 93

DUE
DATE

APR 2 1993

Ref 8HWM FF

EG&G
ROCKY FLATS PLANT
CORRESPONDENCE UNIT

APR 13 12 40 PM '93

ACTION

DIST TR ENC

BENEDETTI, R L	<input checked="" type="checkbox"/>
BENJAMIN, A	<input type="checkbox"/>
BERMAN, H S	<input type="checkbox"/>
CARNIVAL, G J	<input type="checkbox"/>
COPP, R D	<input type="checkbox"/>
CORDOVA, R C	<input type="checkbox"/>
DAVIS, J G	<input type="checkbox"/>
FERRERA, D W	<input type="checkbox"/>
HANNI, B J	<input type="checkbox"/>
HEALY, T J	<input type="checkbox"/>
HEDAH, T G	<input type="checkbox"/>
HILBIG, J G	<input type="checkbox"/>
KIRBY, W A	<input type="checkbox"/>
KUESTER, A W	<input type="checkbox"/>
LEE, E M	<input type="checkbox"/>
MANN, H P	<input type="checkbox"/>
MARX, G E	<input type="checkbox"/>
MCKENNA, F G	<input type="checkbox"/>
MORGAN, R V	<input type="checkbox"/>
PIZZUTO, V M	<input type="checkbox"/>
POTTER, G L	<input type="checkbox"/>
RILEY, J H	<input type="checkbox"/>
SANDLIN, N B	<input type="checkbox"/>
SATTERWHITE, D G	<input type="checkbox"/>
SCHUBERT, A L	<input type="checkbox"/>
SETLOCK, G H	<input type="checkbox"/>
SREPLER, R L	<input type="checkbox"/>
SULLIVAN, M T	<input type="checkbox"/>
SWANSON, E R	<input type="checkbox"/>
WILKINSON, R B	<input type="checkbox"/>
WILSON, J M	<input type="checkbox"/>
ZANE, J O	<input type="checkbox"/>

Gee CV

Buddy MV

Mr Richard Schassburger
Department of Energy
Rocky Flats Office
P O Box 928
Golden Colorado 80402 0928

RE OU 1 IM/IRA

Dear Mr Schassburger

DOE submitted a monitoring plan to EPA and CDH dated June 8 1992 that was established to evaluate the effectiveness of the french drain which was constructed for the Operable Unit 1 (OU 1) Interim Measure/Interim Remedial Action (IM/IRA) This plan included the installation of gauging stations and automatic samplers that were to be installed in the three concrete channels south of the Building 850 parking lot and also in a concrete culvert that is located on the hillside south of Building 850 It is our understanding that these instruments have not yet been installed DOE must explain in writing to EPA and CDH 1) why these instruments are not yet installed 2) when they are scheduled for installation and 3) the budget and cost to date for this portion of the monitoring plan

In addition EPA and CDH have not received any of the quarterly written summaries of data collected as specified on page 3 1 of the monitoring plan DOE should have at least two quarters of data since eleven monitoring wells were installed in August 1992 for this purpose

Your response to these matters is expected to be submitted to EPA and CDH within ten working days of receipt of this letter If you have any questions regarding these matters please contact either Gary Kleeman at 294 1071 or Joe Schieffelin at 692 3356

CORRES CONTROL

R viewed f Address
Co es C t IRFP41393 C
DATE BY

R f l t #

Sincerely

Martin Hestmark
Martin Hestmark EPA
Manager
Rocky Flats Project

cc Paul Singh DOE
Cindy Gee EG&G

Gary W Baughman

Gary W Baughman CDH
Unit Leader
Hazardous Facilities Unit

ADMIN RECORD